

Case Study: Two Gauge Hangers with four Quartz Gauges

Challenge

This job was performed for a customer on the Norwegian sector in order to monitor pressure fluctuations at depth while cutting casing on drill pipe.

Date:

July 2012

Region/Field:

North Sea

Solution

The 13 3/8" Casing was cut with 120 RPM on the cutter while pumping 600-800 l/min. Following the cut, Gauge Hangers and Quartz Gauges were pulled in good condition containing valuable data for the customer

Value Created

This confirms that our new Quartz Memory Gauges will withstand demanding and rough treatment.

